Cornerstone Home Inspections

305-998-8438 OFFICE@CORNERSTONEHISFL.COM WWW.CORNERSTONEHISFL.COM

4-Point Inspection Report



444 sample Miami

Prepared for John Smith

2/20/2020

Ву

Jonathan Velez
License #HI10762

CORNERSTONE HOME INSPECTIONS

4-Point Inspection Form

Insured/Applicant Name: John Smith	Application / Policy #:			
Address Inspected: 444 sample	Miami 00000-0000			
Actual Year Built: 1972	Date Inspected: 4/20/2020			
■ Main electrical service panel with interior door label ■ Electrical box with panel off ■ All hazards or deficiencies noted in this report	Water heater, under cabinet plumbing/drains, exposed valves must complete, sign and date this form.			
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation	must be provided and certified by a licensed electrician.			
Main Panel Type: ✓ Circuit breaker Fuse Total Amps: Unknown Is amperage sufficient for current usage? ■ Yes No (explain)	Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage * If single strand (aluminum branch) wiring, provide details of a Connections repaired via COPALUM crimp Connections repaired via AlumiConn	e of all aluminum wiring): all remediation. Separate documentation of all work must be provided.			
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
General condition of the electrical system: Satisfactory	Unsatisfactory (explain)			
Supplemental information				
Main Panel Second Panel	Wiring Type			
Panel age: Panel age:				
Year last updated: 1990 (EST) Year last updated:				
Brand/Model: Brand/Model:	Other aluminum multi strand,main feed only			

Insp4pt 01 18 Page of

4-Point Inspection Form

HVAC System				
Central AC:				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No				
Supplemental Information				
Age of system: 16YRS (EST) Year last updated: 2013 outside unit (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ■ Yes □ No Is there any indication of an active leak? □ Yes ■ No Is there any indication of a prior leak? □ Yes ■ No Water heater location: Laundry Room				
General condition of the following plumbing fixtures and connections	s to appliances:			
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Insatisfactory Insati	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Unknown Original to home Unknown Completely re-piped Yes 2002 (EST) Partially re-piped (Provide year and extent of renovation in the comments below) Re-piped under sinks	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)			

Insp4pt 01 18 Page of

4-Point Inspection Form

Root (With photos of each roo	f slope, this section can take	e the place of the <i>Roof Inspectic</i>	on Form .)	
Predominant Roof		Secondary Roof		
Covering material: Shingles		Covering material: Roll		
Roof age (years): 1 Year		Roof age (years): 8YRS (EST)		
Remaining useful life (years): 14 Yea	urs	Remaining useful life (years):		
Date of last roofing permit: 6/02/201	7	Date of last roofing permit: Unknown		
Date of last update: 6/02/2017		Date of last update: Unknown		
If updated (check one):		If updated (check one):		
■ Full replacement		■ Full replacement		
☐ Partial replacement		☐ Partial replacement		
% of replacement:	 	% of replacement:		
Overall condition:		Overall condition:		
Satisfactory		■ Satisfactory		
Unsatisfactory (explain below)		Unsatisfactory (explain below)		
Any visible signs of damage / deterior (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Interior ceilings Yes No	S ■ No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No		
Additional Comments/Observations (use additional pages if needed):				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.				
	Home Inspector	License #HI10762	2/20/2020	
Inspector Signature	Title	License Number	Date	
Cornerstone Home	Home Inspector	305-988-8438	_	
Company Name	License Type	Work Phone		

4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Front elevation



Rear elevation



Electrical panel



Electrical panel



Electrical panel



Electrical panel



Electrical panel



Electrical panel



Electrical panel



A/C Unit



A/C Unit Label



A/C Unit


Page of Insp4pt 01 18 Inspector: Jonathan Velez



A/C Unit Label



Water heater



Water heater label



Plumbing system



Plumbing system



Plumbing system



Plumbing system



Plumbing system



Plumbing system



Plumbing system



Plumbing system



Shingles

Inspector: Jonathan Velez Page of Insp4pt 01 18





Shingles Roll roofing



Roll roofing